

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln

Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
1	 An interior photograph of a large, empty gymnasium. The floor is made of light-colored concrete with some debris. A long wall of large, multi-paned windows runs along the right side, offering a view of an outdoor sports field. A brick wall is visible on the left side of the frame.	Innenraum Turnhalle Ansicht Fassade, Bestand  Die Fassade wird ausgetauscht.
2	 An exterior photograph of the gymnasium building. The building features a long, low profile with a prominent wall of large, multi-paned windows. The building is situated on a green lawn under a clear blue sky. A date stamp '25/JUN/2024' is visible in the bottom right corner of the image.	Außenansicht Turnhalle Ansicht Fassade, Bestand
3	 An exterior photograph of the gymnasium building, focusing on a brick gable wall. The wall is made of reddish-brown bricks and has a white light fixture. A long wall of large windows is visible to the right. The building is on a green lawn under a clear blue sky. A date stamp '25/JUN/2024' is visible in the bottom right corner of the image.	Giebelwand Turnhalle

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln

Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
4	 A photograph showing a large brick building under renovation. A section of the gable wall is covered with a dark protective sheet. In the foreground, there is a paved area with a brick pattern. A tractor and other construction equipment are visible near the building.	Giebelwand mit BE-Fläche
5	 A photograph of a paved access area. On the left, there is a gate and a utility box. The area is lined with trees, some of which are bare, suggesting autumn or winter. A car is parked on the right side of the path.	Zufahrtbereich vom Nachtigallenweg zum Haupteingang
6	 A photograph showing a paved area with a gate in the background. A building is visible behind the gate. The ground is covered with fallen leaves, and there are trees on either side of the path.	wie vor mit Blick auf die Toranlage

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln

Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
7		Toranlage Zufahrt Haupteingang
8		Zuwegung hinter Toranlage zum Haupteingang
9		Haupteingang

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln



Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
10		Foyer Haupteingang
11		Foyer Haupteingang mit Glasfassade zum Innenhof  Die Glasfassade bleibt erhalten.

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln




Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
12	 A photograph taken from an interior space looking out through a large glass door. The door is partially open, revealing a paved area with a white radiator on the left. Beyond the door is an inner courtyard with a brick building on the right and a glass-walled structure on the left. The sky is a pale blue, suggesting dusk or dawn.	Tür in Glasfassade zum Innenhof
13	 A wide-angle photograph of the inner courtyard. The courtyard is a rectangular area with a green lawn and some low-lying plants. It is surrounded by brick buildings. On the left, there is a long glass-walled structure. The sky is a clear, pale blue.	Der Innenhof liegt ca. 1,75 m tiefer als OK FFB im Erdgeschoss.

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln

Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
14		Aufsicht Innenhof mit Blick Richtung Haupteingang
15		Fassade nach Ausbau der Verglasung  Das Gerüst wird für die Arbeiten neu gestellt.
16		Ansicht Betonbinder

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln

Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
17	 A photograph showing a grey concrete wall under renovation. To the right, a brick chimney is visible. Scaffolding with blue safety railings is positioned against the wall. The sky is overcast.	wie vor
18	 A close-up photograph of a grey concrete surface. A blue protective strip is applied along the bottom edge. The surface shows some minor texture and discoloration.	Oberfläche Betonbinder, exemplarisch
19	 A close-up photograph of a grey concrete surface, similar to image 18. A blue protective strip is visible at the bottom. There is some surface damage or peeling of the concrete in the upper part of the frame.	wie vor

**Projekt: Sanierung der Turnhalle, Nachtigallenweg 86 in Bonn**

Bauherr: BLB NRW Köln, Domstraße 55-73, 50668 Köln

Anlage: Fotos Bestand

Bild-Nr.	Bild	Beschreibung
20		Betonschäden, exemplarisch
21		wie vor
22		wie vor